

ANDOORKONAM GRAMA PANCHAYATH

FITNESS CERTIFICATE FOR SCHOOL

9. Name of School : MODEL PUBLIC SCHOOL CRPF, TVPM
10. Name of the Officer : ASST ENGINEER
11. Period for which the Certificate is issued : 2021-2022 MARCH
12. Classification of the building and Size (basis for classification) (See Annexure 1)
- IV. Permanent Single or Multistoried : Permanent Multistoried
- V. Semi-Permanent (27.5 x 5.5.0 x 3.60) (GF & FF)
- VI. Temporary shed (38.5 x 5.5 x 3.60) (GF + FF & SF)
13. Nature of defects if any
- h) Foundation and Basement
- i) Super-structure
- j) Doors and windows NIL
- k) Wood work wrought put up
- l) Roof
- m) Flooring
- n) Miscellaneous (Cracks etc)
14. Any Major defects noticed which will render the building unsafe in any manner : NIL
15. Whether maintenance works have been done properly. : YES
16. Whether the structure is sound or not For conducting classes : YES (The Structure is Sound for conducting classes under normal Weather conditions)

Note- 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc..

2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on26/03/2021..... And found to be fit to conduct classes for the period 2021-2022 AY.....For the reasons stated above.

Place KANIYAPURAM

Date 27/03/2020

Signature:

Assistant Engineer
LSGD, Section
Andoorkonam Grama Panchayat



STRUCTURAL STABILITY CERTIFICATE

Name of the School : Model public school, Technocity west,
Pallipuram

Village ,Town , District


In which the school is situated : Survey No. 376/12, 376/14-1, Pallipuram
Village , Thiruvananthapuram

**The area on which the classes
Are running** : 3586.4 Sqm

**Building Nos From Panchayath/
Authority** : Andarkonam Grama panchayath
1/428 , 1/229

I certify that I have inspected the school building on 15/03/2021 referred to the above and examined the various parts including foundation ,columns, beams etc. I am of the opinion that the buildings are structurally sound and their stability will not be endangered by their use as School.

Vahuthacaud,
23/03/2021


DINESH .R , ME structural
Reg No: 081038129006 / 2010
Anna University Colmbatore



Reg No. 081038129006

*The Syndicatē of the Anna University Coimbatore hereby makes known that **DINESH.K** has been admitted to the **DEGREE OF MASTER OF ENGINEERING** in **STRUCTURAL ENGINEERING** under the Faculty of Civil Engineering having completed the prescribed programme of study and having been certified by duly appointed examiners to be qualified to receive the same and having been placed by them in the **FIRST CLASS** at the Examination held in **MAY 2010.***

ANNA UNIVERSITY COIMBATORE ANNA UNIVERSITY COIMBATORE ANNA UNIVERSITY COIMBATORE ANNA

Given under the Seal of the University



Coimbatore 641 047
India
February 2011

[Signature]
Controller of Examinations

[Signature]
Registrar

[Signature]
Vice-Chancellor